

ANEXO I

Cuadro 5: **Bienes asociados de la quebrada Cañada, margen derecha.**
(Coordenadas en UTM WGS-84, Zona 19 S)

Limite Superior de la Faja Marginal - LSFM						Limite Superior de la Ribera - LSR	
Vertice	Codigo	Progresiva	Este	Norte	Ancho	Este	Norte
1	-	-	481700.22	8609731.03	3.00	481697.95	8609729.07
2	HMD_001	0+008	481705.91	8609724.45	3.00	481703.57	8609722.56
3	-	-	481732.52	8609691.16	3.00	481730.17	8609689.29
4	-	-	481758.30	8609657.14	3.00	481755.89	8609655.36
5	-	-	481790.55	8609614.84	3.00	481789.63	8609611.12
6	HMD_002	0+199	481834.34	8609634.49	3.00	481832.91	8609630.79
7	-	-	481867.27	8609574.56	3.00	481864.65	8609573.09
8	-	-	481892.72	8609530.41	3.00	481892.57	8609526.13
9	-	-	481907.76	8609553.73	3.00	481910.22	8609551.99
10	-	-	481925.15	8609561.92	3.00	481923.93	8609558.40
11	HMD_003	0+397	481945.11	8609532.90	3.00	481942.63	8609531.20

Cuadro 6: **Bienes asociados de la quebrada Cañada, margen izquierda.**
(Coordenadas en UTM WGS-84, Zona 19 S)

Limite Superior de la Faja Marginal - LSFM						Limite Superior de la Ribera - LSR	
Vertice	Codigo	Progresiva	Este	Norte	Ancho	Este	Norte
1	-	-	481693.41	8609725.14	3.00	481695.68	8609727.11
2	HMI-001	0+011	481698.91	8609718.78	3.00	481701.24	8609720.67
3	-	-	481739.87	8609667.67	3.00	481742.23	8609669.53
4	-	-	481761.43	8609638.46	3.00	481763.81	8609640.30
5	HMI-002	0+152	481787.79	8609603.69	3.00	481788.71	8609607.40
6	-	-	481830.04	8609623.39	3.00	481831.47	8609627.10
7	-	-	481847.96	8609590.62	3.00	481850.57	8609592.09
8	-	-	481869.22	8609553.00	3.00	481871.84	8609554.47
9	-	-	481892.70	8609517.96	3.00	481892.64	8609522.05
10	-	-	481905.00	8609529.68	3.00	481902.58	8609531.51
11	-	-	481916.07	8609549.67	3.00	481914.32	8609552.26
12	-	-	481921.49	8609551.35	3.00	481922.71	8609554.88
13	HMI-003	0+397	481937.69	8609527.80	3.00	481940.16	8609529.50